



1E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

Generton

Rpt.

Sld

No.

31982

Marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

e of Engine

Triple Expansion

If Boilers fitted with forced draught

Main Boilers — yls

Aux Boilers — ~~no~~

Tail Shaft. If fitted with a continuous liner

yls

If fitted with an outside gland of  
approved type }

no.

This vessel's machinery appears to have been built in accordance  
with the Rules and the approved plans, and it is submitted she is  
eligible to be classed + Rule 12.36.

2 S.B (F.D. Spt)

~~18.12.36~~

DB 220th

ylee

Sld

18.12.36

Yun

18.12.36

Accounting E.L. report.

certificates not to be handed over  
until Survey satisfactorily completed



© 2021

Lloyd's Register  
Foundation

011912-011926-0200