



/P.

LLOYD'S REGISTER OF SHIPPING

Collingwood Buildings, Newcastle upon Tyne, 1

Telegrams: Register, Newcastle upon Tyne

Telephone: 21391 (3 lines)

2nd November, 1965.

Reference

C.
RNC

The Secretary,
London.

4 - NOV 1965
23

Dear Sir,

Motorship "ADAMS BECK".

With reference to your letter of the 1st November, a further cursory examination has been carried out on the holds of the above ship in view of the request that this vessel make one further trip to Greece with cargo, and we would recommend that the double bottom tanks be tested before sailing, and that in all holds various rivets through the hopper side tank top plating which were found to be leaking should be welded, and fractures in the hopper side tank top plating should be temporarily repaired and some frames in all holds where fractured should be temporarily strapped.

All the above work could be done afloat.

We are, Dear Sir,
Yours faithfully,
THE SURVEYORS.

per

H. H. Howie

*Also report received for a/c
17.11.65
M.B.S.*



© 2021

Lloyd's Register
Foundation

011988-011994-0180

