


COPY

Copied to Gothenburg

## LLOYD'S REGISTER OF SHIPPING



Port

HAMBURG

Date

8th May, 1962

This is to Certify that I have

Surveyed the M.S. "FREDRIKA" 2937 tons gross of Stockholm, whilst the ship lay in floating dock at Hamburg on the 3rd May, 1962 and subsequently on account of Advancement of Special Survey, Docking, Damage and Repairs

and that I am transmitting to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, also that I am Recommending that she be retained as now classed with fresh record of DS 5.62, subject to all outstanding conditions which are at present attached to the ship's class being dealt with as previously recommended.

(J. Guntzler)

Surveyor to Lloyd's Register.

## KEY TO ABBREVIATIONS

AS Annual Survey  
BiS Biennial Survey  
DS Docking Survey  
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey  
SS(Dr) Hull Special Survey (Drilling)  
SS(M) Hull Special Survey (Modified)  
SS(P) Hull Special Survey (Progressive)

p.t.o

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B) 130m,9,60 (MADE AND PRINTED IN ENGLAND.)

© 2021

Lloyd's Register  
Foundation

011988-011994-0271



Copied to Rotterdam

COPY

# LLOYD'S REGISTER OF SHIPPING

Now Done for Advancement of Special Survey:-

Examined internally:-

Stern tank.

Freshwater tank on top of after peak tank.

Port

Examined:-

Rudder lift.

Date



This is to Certify that I have

Surveyed the U.S. S.S. 'HAWAIIAN' 2527 from Exam of Stockholm, which

was only in floating dock at Hamburg on the 2nd day, 1925 and

subsequently on account of advancement of Special Survey, 1925.

George and Regatta

and that I am transmitting to the Committee of Lloyd's Register of

Shipping, London, a Report, stating that all repairs recommended by

me have been completed to my satisfaction, also that I am

Recommending that she be

at 10.00, subject to all outstanding conditions which are at

present attached to the ship's papers being dealt with as previously

recommended.

at 10.00, subject to all outstanding conditions which are at

present attached to the ship's papers being dealt with as previously

recommended.

at 10.00, subject to all outstanding conditions which are at

present attached to the ship's papers being dealt with as previously

recommended.

at 10.00, subject to all outstanding conditions which are at

present attached to the ship's papers being dealt with as previously

recommended.

at 10.00, subject to all outstanding conditions which are at

present attached to the ship's papers being dealt with as previously

recommended.

at 10.00, subject to all outstanding conditions which are at

present attached to the ship's papers being dealt with as previously

recommended.

at 10.00, subject to all outstanding conditions which are at

present attached to the ship's papers being dealt with as previously

KEY TO ABBREVIATIONS

AS	Annual Survey
BS	Biennial Survey
CS	Cargo Survey
MS	Cargo Batches not fitted (No Sparring)
SS	Hull Special Survey
SS(D)	Hull Special Survey (Dull)
SS(M)	Hull Special Survey (Modified)
SS(P)	Hull Special Survey (Progressive)



This Certificate is issued upon the basis of the Rules and Regulations of the Society, which provide that:-  
"While the Committee of the Society is endeavoring to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."  
It is to be responsible for other parts of the Survey or the Surveyor's Certificate B.1.