

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic (Inland: Committee, London, Telex
Address (Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

18th November, 1963.

Dear Sirs,

C.
DHGK/DET

S.S. "LEONIDAS CAMBANIS"

Reports of surveys held at Hamburg and Buenos Aires have now received the consideration of the Committee, and a record of Drydocking 7.63 and notations of Screwshaft Examined 7.63 and Main Boiler Survey 8.63 have been assigned.


In the meantime class has been continued subject to:-

1. Main engine L.P. cylinder stuffing-box, main condenser water box and main circulating pump casing (Metalock 8.63) being examined by the end of January 1964.
2. Propeller and outside fastenings being specially examined at the next drydocking.

Yours faithfully,

Deputy Clerk to the
Classification Committee

Messrs. S. G. Embiricos Ltd.,
Dunster House,
17-19 Mark Lane,
LONDON, E.C.3.



© 2020

Lloyd's Register
Foundation

011995-012002-0119