

(Req. 1a.)

(Received at London Office 19.....)

No. 1154 Place Hendrik-Ido-Ambacht Date 1st April, 19 52.

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to Specially Survey during Construction the Hull, ~~Engines and Boilers~~ of the Vessel No. 270 building by Messrs. C.V. Scheepswerf & Gashouder-bouw JONKER & STANS for Messrs. Indonesian Government of Tons. Length 114.83', Breadth 21.33', Depth 9.66' intended to be Classed 100 A 1 "For Service in the Indonesian Archipelago"

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connection therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Engine Makers..... N. V. Werkspoor - Amsterdam

Boiler Makers.....

Signature.....

To the Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street, London, E.C.3.

COMM. VENNOUSCHAP
SCHEEPWERF EN GASHOUDERBOUW
JONKER & STANS

NOTE.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—

"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

have been tested under pressure and found tight there