

Surveyed After
Cell DBor DBor

COPY OF AIR LETTER

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, E.C.3

Extract from Kobe Classing Letter dated 4.5.54.

1968 "EMPIRE VICEROY". This case has today been submitted to the Committee and a notation of "Laid up pending machinery repairs and surveys overdue" is being entered in the Register Book.

I shall be glad if you will confirm your statement that there are only two bower anchors on board, as it would appear from the reports that the full complement of bower anchors should be on board.



© 2021

Lloyd's Register
Foundation

012019-012026-0216