

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

ORD SURVEYOR MONTEVIDEO URUGUAY (22.6.60)

REMAR LOADLINE RENEWAL SURVEY REQUIRED FOR ISSUE LIST VALID END SEPTEMBER
NEXT INCLUDES EXAMINATION OF HULL STRUCTURE INTERNALLY AND EXTERNALLY SIMILAR
SCOPE TO SPECIAL SURVEYS STOP REPAIRS RECOMMENDED BY YOU TO MAINTAIN
SHIPS STRUCTURAL EFFICIENCY AND SEAWORTHINESS MUST BE EFFECTED NOW INCLUDING
SHELL PLATING AND SHELL RIVETING STOP NO CERTIFICATE SHOULD BE ISSUED

Cont'd....



© 2021

Lloyd's Register
Foundation

012142-012147-0163 1/2

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

Page 2 SURVEYOR MONTEVIDEO URUGUAY
(22. 6.60)

ESS ALL THESE REQUIREMENTS FULFILLED WRITING
COMMITTEE



© 2021

Lloyd's Register
Foundation

0163 ²/₂