

"OREMAR"

IT IS SUBMITTED the following cable be
sent to the Montevideo Surveyor :-

OREMAR LOADLINE RENEWAL SURVEY REQUIRED FOR ISSUE LLST VALID END
SEPTEMBER NEXT INCLUDES EXAMINATION OF HULL STRUCTURE INTERNALLY
AND EXTERNALLY SIMILAR IN SCOPE TO SPECIAL SURVEYS STOP REPAIRS
RECOMMENDED BY YOU TO MAINTAIN SHIPS STRUCTURAL EFFICIENCY AND
SEAWORTHINESS MUST BE EFFECTED NOW INCLUDING SHELL PLATING AND
SHELL RIVETTING WRITING

COMMITTEE

Wm

W.M.



© 2021

Lloyd's Register
Foundation

012142 - 012147 - 0169