


It is submitted the following cable be
sent to the Montevideo Surveyor -
loadline renewal

OREMAR, Survey required for ISSUE

LLST. VALID END SEPTEMBER NEXT

includes examination of hull structure
internally and externally similar in
scope to special survey stop & repairs
recommended by you to maintain ships
structural efficiency and seaworthiness
must ~~repeat must~~ be effected now
including shell plating and shell

unwetting writing



© 2021

Lloyd's Register
Foundation

012142-012147-0165