

REG. BK.

548

E CARRIER

F REGISTRY

TONNAGE

POSTPONED SURVEYS

SHIP'S NAME

XX

M.S.

"OREMAR"

BUILT

12-1934

LAST DOCKING

1.59.

L.L. CERT. EXPIRES

28.2.60.

A.L.L. SURVEY DUE

s) and/or conditions
under review

Special Survey due 2.59. postponed until 2.60 and 5.60.
Donkey Boiler Survey due 7.60.

ending items
ly held)

Machinery limit by 8.60:- See endorsement 25.1.60.

gements
agreed

Postponement of Special Survey until 2.60 approved 22.10.59 (G.E. B.As. 8.59.). On 26.1.60. the Owners' Agents stated, and the Buenos Aires Surveyors confirmed, that serious difficulties were being encountered due to lack of drydocking facilities in Argentina and the Owners requested that the period of grace granted until February, 1960 be extended for a reasonable period. The case was considered by the Committee on 5.2.60. and the Buenos Aires Surveyors were instructed to inform the Owners that as the year of grace expired at the end of 2.60. they must make definite arrangements to carry out the Special Survey before the end of 5.60. or alternatively, to hold the Special Survey as far as practicable afloat, and to postpone only the drydocking portion until 8.60.

proposal

POSAL The Owners have been advised of the Committee's previous decision and state that they cannot comply with the Special Survey requirements. They now require extension of class until 9.60. (7 months after the expiration of the year of grace). The Montevideo Surveyors cannot recommend renewal of the Freeboard Certificate as the necessary repairs cannot be effected in the time available. The Owners intend to sail the ship on the 17th June and as nothing has been prepared for survey no internal examination is possible.

FRIDAY 17 JUN 1960

tee

Submitted further particulars of accident and repairs be furnished before consideration.

2021
Lloyd's Register
Foundation

012142-012147-0171