

COPY.

THROUGH MALTA.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C.3.

30th May, 1951.

Classn.
(S)

G B H M

Dear sirs,

S.S. "VALETTA CITY"

The Committee have had before them a report from the Society's Surveyors at Cardiff, from which it is noted that this vessel was examined afloat in February/April last, repairs effected and the Boiler Survey carried out.

The Surveyors report that locally wasted stay and plain tubes were found in all the boilers, and they recommend that these tubes should be renewed not later than the end of next month.

In confirming this recommendation, the Committee have continued the vessel's class, subject to this matter receiving attention by the time stated, and for your information I may add that her class is also subject to the sole piece of the sternframe (previously repaired) being specially examined at the next drydocking, when permanent repairs require to be carried out to shell plates Nos.5 in 2nd, 3rd and 4th strakes below sheer on the starboard side; 30 fathoms of chain cable also require to be supplied at the earliest opportunity.

Yours faithfully,

Copy sent Malta.

Clerk to the
Classification Committee

Messrs. Pace Bros. Ltd.,
Valetta,
MALTA.

Lloyd's Register
Foundation