

"ATHAMAS"

AMS

24863.

CLASS IS SUBJECT TO: Temporary repairs to Main  
Engine port side column in way of HP cylinder  
being specially examined by 5.62 (6 months  
limit).

---

Before this case receives consideration, the  
Surveyor should be requested to state whether the  
Special Reasons List item as per London cable  
dated 26.6.62 received attention.



© 2021

Lloyd's Register  
Foundation

13.8.62.