

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen, London

Telephone: ROYal 9166

Enclosure:

3rd October, 1958.

(S)
Dear Sirs,

Steamer "ATHAMAS"

A report has been received from the Society's Alexandria Surveyor of the Special Survey held between April and June last, and I have the pleasure to enclose the official Classification Certificate in respect of the machinery.

During the survey 45 fathoms of the chain cable on board were found worn. In addition the ship is deficient of 30 fathoms of chain cable. The Committee have continued class subject to the 45 fathoms of worn cable being renewed and 30 fathoms of cable being supplied and verified at the earliest opportunity.

When this equipment has been dealt with the ship will be eligible for the notation SS Alx. 7,58. I shall be glad to learn, therefore, what early arrangements you propose to make with regard to this equipment.

Class is also subject to the fractured rudder post (electrically welded and re-inforced 6,58) being examined at the next drydocking, and to the propeller being specially examined or renewed at the first drydocking.



© 2021

Continued/...

Lloyd's Register
Foundation

eamer "ATHAMAS"

- 2 -

3rd October, 1958.

Records of Drydocking and Screwshaft Examined
5,58, and Main Boiler Survey, Steam Pipe Survey
and Engine Survey, all with date of 7,58, have
been assigned.

Yours faithfully,

Assistant Clerk to the
Classification Committee.

Messrs. N. & J. Vlassopoulos Ltd.,
Bevis Marks House,
BEVIS MARKS,
London, E.C.3.



© 2021

Lloyd's Register
Foundation