

COPY

LLOYD'S REGISTER OF SHIPPING

Report No. 4954

Port ALEXANDRIA

4th July 1958

ORIGINAL BEARS REQUIRED REVENUE TAX STAMP.

This is to Certify that I have

Surveyed the Machinery of the S.S. "ATHAMAS" ex "Marilena"
4725 tons gross of PUERTO LIMON, whilst lying afloat and in
Dry dock at Alexandria, on the 19th April 1958 and subsequently,
for Engine Special Survey and Damage Repairs, Boiler Survey,
Steam Pipe Survey and Tailshaft Survey.

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also

that I will Recommend that in the case of this Vessel the following

Survey Records be made in the Supplement to the Register Book
Engine Special Survey, 7/58, Boiler Survey 7/58, Steam Pipe
Survey 7/58 and Tailshaft Survey - Continuous Liner 5/58.

and that her Machinery Classification Record be continued in the Book.

Parts now examined:

(C.S. Items only)

(D.J. Haniotis)

Acting Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MB	Main Boiler Survey	TSN	Tailshaft renewed
MS	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
FP	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"Where the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."