

COPY

LLOYD'S REGISTER OF SHIPPING

TRINIDAD, B.W.I.

23rd January, 1955

THIS IS TO CERTIFY that

J.B. STARK

the undersigned Surveyor to this Society did at the request of

the Master, and on instructions from Messrs. Geo. F. Huggins & Co., Ltd., (Lloyd's Agents) survey the S.S. ESSO AVILA, 3676 tons gross of Maracaibo, on the 21st January, 1955, and subsequent dates, whilst the ship lay afloat at Port of Spain, Trinidad, for the purpose of ascertaining the nature and extent of damage stated to have been caused whilst tying up alongside vessel SOYA ATLANTIC, at Guaria, Venezuela, on the 8th January 1955 at 2130 hours whilst engaged on bunkering duties.

For further particulars see Log Books.

The undersigned, upon examination:-

Found

(1) Starboard aft inboard double bollard broken across the base, at the root of the aft bollard of same.


(2) Hardwood pad in way of bollard badly cracked and broken.

Recommended

As a new bollard was available, it was recommended that this be fitted.

Renew same.

The above repairs have been carried out to my satisfaction and can be considered permanent.



Surveyor to Lloyd's Register of Shipping.



© 2021

Lloyd's Register
Foundation

01224-012220-0008