

COPY

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER



Port Aruba, N.W.I.

January 7th., 1954

This is to Certify that

W.D. WARDLE

the undersigned Surveyor to this Society did at the request of the Owner's Representative, attend on board the Steel Twin Screw Steamer

"ESSO AVILA"

3676 tons gross of Maracaibo, Venezuela, on November 5th., 1953 and subsequent dates, as she lay on the Slipway at San Nicholas Harbour, Aruba, N.W.I. in order to examine and report on the nature and extent of damage to the vessel, stated to have been sustained in consequence of vessel contacting Dolphin at La Arriaga, on February 13th., 1953.

For Further particulars please see vessels Log Book.

On examination the following was

Found

Recommended

Starboard side

"J" strake plate No 14 from aft, indented between three shell frames in way of starboard side of Pump Room.

To be faired in place.

"K" strake plate No. 8 Lightly indented in way of indented area of "J" strake plating

To be faired in place.

*W.D. Wardle*

Surveyor to Lloyd's Register of Shipping

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."