

COPY.

Lloyd's Register of Shipping.



Port Baltimore, Maryland

11th April, 1946

This is to Certify *that I have*

Surveyed the Boiler and Machinery of the Steel Twin Screw Steamer

"TASAJERA"

3677 tons gross of Panama, for drydocking and * L.M.C. Surveys

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have

Recommended *that the records of* * L.M.C. 4,46 and Port and starboard Tail Shafts (CL) seen 3,46

be made in the Register Book in the case of this vessel, when steam pipes have been examined and tested.


(Signed) A Maybank

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

10M-5-42 Printed in U.S.A.



Lloyd's Register
Foundation

012211 - 012220 - 0029