

2

Sent to Chief Surveyors _____

Received from Chief Surveyors **15 SEP 1948**

VESSEL'S NAME **EASTBURY**

Report *gls.* No. **Y3154**

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Clasing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Clasing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/42.)

(Amudical No. Special) SURVEY ^(A) PARTLY HELD. *(No. 9.47) Doeb*

When due **5.47.** When proposed to be completed *conversion to D.F.*

Portion of Survey held, &c. *All items.*

Noted
ADM.
10-9-48.

8,48 gls.
'S.S. gls. 8,48.'

Insert in R.B.

'Fitted for oil fuel 8,48 F.P. above 150°F.

Delete from R.B.

'Cargo battens not fitted.'



© 2021

Lloyd's Register
Foundation

01221-01218-0052