


COPY *London*

# LLOYD'S REGISTER OF SHIPPING

6620



Port..... SOURABAYA .....

Date..... 5th March, 1965. .....

**This is to Certify** that I have surveyed part of the machinery of the M.V. "GILIJANG" 997 gross tons of Kalianget for Part B.S. whilst the vessel lay afloat in Dry Dock at this Port on the 10th October, 1963 and subsequently part of and that ~~all~~ my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the ~~machinery classification should be retained~~ and the following survey records assigned TS/OG (5/64) now, special survey incomplete class suspended (12/64), subject to any outstanding condition of class being dealt with as previously recommended.

Parts now examined:—

Dry Dock : Tailshaft, propeller, sea connections and outside fastenings.

Main Engine :

No 1 to 10 cylinders, covers, pistons & rods, valves & gears, top ends, crankpins & bearings.

No 1 to 11 journals & bearings.

Both Lub. Oil pumps.

Auxiliaries :

Both Freshw. Cooling pumps (Starb.)

Both main freshw. coolers

Port Lub. oil cooler

Port Forward aux. air receiver and safety devices.

P.T.O.

*For S.R. Khare and Self.*

S.R. KHARE & R.L. SOEI.

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150°F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

