

COPY

# LLOYD'S REGISTER OF SHIPPING



Port

N.A.P.L.E.S. (Italy)

27th September, 1962

This is to Certify that I have  
surv. "PUNTA RONCO" 7878 tons gross,

Surveyed the Machinery of the  
of Genoa, whilst afloat, and in Drydock, at Naples, on 13th Aug.,  
1962 and subsequently

and that I will transmit to the Committee of Lloyd's Register of  
Shipping, London, a Report stating that all recommendations made by  
me in connection therewith have been carried out to my satisfaction; also  
that I will Recommend that in the case of this Vessel the following  
Survey Records be made in the Supplement to the Register Book  
ABS.8,62 now and CS.(with date) on completion of Survey.

and that her Machinery Classification Record be continued in the Book.  
subject to main engine FW cooler being hydraulically tested when  
fitted on board.

## Parts now examined:

(C.S. Items only)

Main Engine :- Nos. 1 & 6 Cylinders, covers, pistons & rods,  
valves & gears, crankpins & bearings, and  
No.1 Journal and bearing.

Intermediate Shaft and No.2 bearing.

S.Upper FO boiler service pump.

S.Fwd. FO transfer pump

S.aft General service pump.

S.Fwd.Aux. engine jacket cooling pump.

P.Bilge & fire pump in Fwd. pump room

(P.T.O.)

Carlo Stare M.V. Pollio  
(C.Stare) & (M.V.Pollio)

Engineer Surveyor to Lloyd's Register

## KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey  
CS Continuous Survey of Engines  
DBS Donkey Boiler Survey  
ES Engine Special Survey  
MBS Main Boiler Survey  
MES Modified Survey of Oil Engines  
OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey  
SPS Steampipe Survey  
TS Tailshaft Survey  
TS(CL) Tailshaft Survey—Continuous Liner  
TSN Tailshaft renewed  
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,3,59 (MADE AND PRINTED IN ENGLAND.)

012229- 012235- 0018



COPY

## LLOYD'S REGISTER OF SHIPPING



P. Bilge & fire pump in Engine Room.  
 S. Fwd. (N.2) SW cooling pump.  
 M.E. FW aux. cooling pump. Port  
 M.E. Turning gear  
 P. Upper & lower air receivers and safety devices.  
 Aux. air receiver.  
 Evaporator (Safety valves not tested under steam)  
 Windlass.

*Carlo Stare* *Ch. V. Pollio*  
 (C. Stare) & (M.V. Pollio)

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book

and that her Machinery Classification Record be continued in the Book.

Parts now examined:  
 (C.S. Items only)

Main Engine: Nos. 1 & 2 Cylinders, covers, pistons & rods, valves & gears, crankpins & bearings, and No. 1 Journal and bearing.

Intermediate Shaft and No. 2 bearing.

Upper 30 boiler service pump.

Fwd. FO transfer pump.

Star General service pump.

Fwd. Aux. engine jacket cooling pump.

P. Bilge & fire pump in Pwd. pump room

(P.T.O.)

Engineer Surveyor to Lloyd's Register

## KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey
CS	Continuous Survey of Engines
DBS	Donkey Boiler Survey
ES	Engine Special Survey
MB	Main Boiler Survey
MS	Modified Survey of Oil Engines
OF	Fitted to oil (Lubrication) F.P. above 150°F.
TS(O)	Tailshaft Survey—Oil Gland
TSN	Tailshaft Survey—Continuous Line
TS(C)	Tailshaft Survey
TS	Steam Generator Survey
SGS	Steam Generator Survey

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
 "While the Committee of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracies in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment or delay in the performance of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. No. 1) 120m. 22 (MADE AND PRINTED IN ENGLAND)

Repairs

Lit. 8.000

Date when A/c. Rendered