

18 OCT 1962

4E

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME....."PUNTA RONCO".....REPORT.....NAP.....No. 7479..

CSM advanced.

ABS due 1.62. Now held.

Docking.

The Surveyor reports the Main Engine fresh water cooler tubes corroded and the tube nest now removed ashore for repairs and the Surveyor recommends that the class be made subject to the main fresh water cooler being tested upon re-installation aboard the vessel.

IT IS SUBMITTED that this vessel is eligible to remain as classed with fresh record of ABS 8.62 now, subject as recommended.

JN

16.10.62.NOTE.

It is concluded but should be confirmed by the Surveyor that the windlass was examined as stated on the Interim Certificate as this item has been omitted from the Report.

Yes.
(Nat. ltr 25/18/62)



© 2021

Lloyd's Register
Foundation

012229- 012235-0019