

COPY

LLOYD'S REGISTER OF SHIPPING



Port BOMBAY

23RD AUGUST 1963.

This is to Certify that I have surveyed part of the machinery of the "VARIDA" Gross tons 416

for while being installed at Bombay by Mazagon Dock Ltd.,

and that all ~~our~~ ^{our} recommendations have been carried out to ~~my~~ ^{our} satisfaction. We are ~~our~~ ^{our} reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery ~~classification should be retained and the following~~

~~service records assigned~~ be classed in the Register Book with record of + LMC 5-63 and notation of OIL ENG, OG and Torsional Endorsement "Machinery not to be operated continuously below 150 r.p.m. or between 450 and 515 r.p.m." when the survey has been completed.

Parts now examined :—

NOTE: To complete the survey the following remains to be done.

The main cables from both generators to switchboard to be replaced by cables of Rule capacity.

The ship to ship electrical circuit to be installed with cable of Rule capacity.

A notice board to be fitted at shore supply connecting box on deck.

The main engine tachometer to be marked with the barred speed range in red.

One jet nozzle to be supplied for engine room fire hose and one additional nozzle to be supplied on deck.

R. McIntosh
S. Ratra

Surveyor to Lloyd's Register of Shipping
(R. McIntosh & S. Ratra)

KEY TO ABBREVIATIONS


ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150°F	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert.B.I.

City Press, Calcutta.



© 2021

Lloyd's Register Foundation

012229-012235-0096