

F.E.

has not

by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

SHIP NAME Stl. sc. "JOLLY DAYS" Rpt. Abn No. 18037

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.

Length No. <u>1237</u>	Depth "d" <u>8.5 to U Dk</u> <u>12 to R.Q.Dk</u>
Beam No. <u>4494</u>	Proportions = <u>L</u> <u>13.7 to U Dk</u> <u>D</u> <u>10.01 to R.Q. Dk</u>
Plating <u>Angle frames as approved</u>	Sheerstrake <u>as approved</u>

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100A1

1 Dk

Side tanks aft 14' 40t, FPT 43t, APT 21t

FK, 3 H, Cem., Lloyd's A & CP

Q 83', F 20'

Machy. aft



© 2021

Lloyd's Register Foundation

... Certificate of Classification to be endorsed "Cargo battens not ..." and the same notation to be entered in the Register Book.

012229-012235-0171

