

Lloyd's Register of Shipping

Tollbodgaten 27



Reference

Eng.....

Enclosure.

RECEIVED

24 SEP 1951

Ansd.....

Dear Sir,

M.V. "SANTO".

In reply to your letter of the 11th instant we have to confirm that the electrical arrangements are generally in accordance with your sketch which is returned herewith, also that it is not intended that the two generators should run in parallel.

The switches marked A & B on the plan perform no useful function but are connected in the circuit.

Yours faithfully

THE SURVEYORS

PER.

The Secretary,
London.



© 2021
Lloyd's Register
Foundation
012246-012255-0040

ENG.

HB
Noted
in installation in the circumstances stated the electrical
is considered such as could be accepted
in this instance.
J. A. Bear
25. 9. 51.
Engineer Rob (F.E.)

