

m.v. "SANTO"


IT IS SUBMITTED the Oslo Surveyors be informed that the plan has been re-examined in conjunction with their remarks.

The schematic wiring diagram of the main switchboard is still obscure; ~~but~~ it is concluded ^{but should be confirmed} that the arrangements are generally in accordance with the attached sketch, and that it is not intended that the two generators will be run in parallel. The function of the switches marked A & B on the plan is not clear.

The Surveyors comments on the foregoing might be requested.




6th September, 1951.



Return 1 copy of plan for reference, together with sketch.

Retain 2 copies of plan and sketch.

Engineer Reports (FE) re test certificates



lr 11/9



© 2021

Lloyd's Register
Foundation

012246-012255-0042