


COPY

LLOYD'S REGISTER OF SHIPPING



Port of Piraeus,

20th August, 1960.

This is to Certify that I have

Surveyed the Machinery of the S.S. "HELLAS" ex. "TAROONA" 4326 tons
going afloat & in the drydock at Piraeus
on the 10th December, 1959 & subsequently on account of Completion
of Continuous Survey of machinery, Part Boiler Survey, and
Commencement of new C.S. cycle,

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also
that I will Recommend that in the case of this Vessel the following
Survey Records be made in the Supplement to the Register Book
C.S. 3,60 now M.B.S. 3,60 on completion and C.S. (with date)
on completion of the new C.S. cycle

and that her Machinery Classification Record be continued in the Book.
without condition regarding the repairs to the stbd. HP turbine.

Parts now examined;

(C.S. Items only)

Stbd. HP & LP turbines, reduction gearing & holding down bolts
and chocks.
Stbd. main condenser.
Port & stbd. air ejectors, main & auxiliary.
All (three) auxiliary condensers.
All HP, IP & LP feed heaters.
Bilge Pump.
Aux. Bilge Pump.
Emergency Bilge pump (Boiler Room).

P.T.O.

A. Blakeman
Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CS Continuous Survey of Engines
DBS Donkey Boiler Survey
ES Engine Special Survey
MBS Main Boiler Survey
MES Modified Survey of Oil Engines
OF fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
SPS Steampipe Survey
TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be
understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any
inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society
for any error of judgment, fault or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents
of the Society."

Port. B.1.) 150m, 3,59 (MADIAND PRINTED IN ENGLAND.)

© 2021

Lloyd's Register
Foundation

012265-012272-0047

and hand

Port M.E. MP & LP turbines, reduction gearing and holding down bolts and chocks.
Stbd. ME HP turbine, reduction gearing and holding down bolts and chocks.
Port main condenser.
All (4) main circulating pumps.
Both auxiliary circulating pumps (for aux. steam turbines)
Both sanitary and fire pumps (Boiler Room).
Distiller FW pump.
The ~~aux~~ reciprocating feed pump.
Both main extraction pumps.
HP & LP evaporator (Safety Valves not adjusted).
Windlass (Electrical).
Electrical installation.