

COPY.

FOR LONDON.

18 OCT 1951

Lloyd's Register of Shipping.



Port SYDNEY N.S.W.

3rd October, 1951.

This is to Certify that I have

Surveyed the T.S.S. "TAROONA" of Melbourne

4297 tons gross.

afloat and in Dry Dock for Special Survey and Load Line
Renewal.and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report, stating that all repairs
recommended by me have been completed to my satisfaction, andthat I have **Recommended** that she be continued as now
classed subject to electric welding of cracked rudder head
flange being specially examined at next dry docking and have
record of Dry Docking 9,51 and Notation of S.S. Syd. 9,51

dry and perishable cargo.

being fit to carry

ENDORSEMENTS. Shell plates No. 4 & 6 in 2nd and 3rd strakes below
sheer (ps) set in. Indents in Keel and bottom shell plating
(p & s).

(Sgd) F.K.L. Birk.

Surveyor to Lloyd's Register

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society's Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, fault or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

L. B.)

10M-11/4B-J. & O'S. (PRINTED IN AUSTRALIA)

© 2021
Lloyd's Register
Foundation

01265-01272-0069