

13 JUN 1961

Received from Chief Ship Surveyor

P'S NAME "SLITAN" REPORT IST No. 5030

EA

standing Conditions of Class: NONE

ACTION is DEFERRED for examination
in dry dock after grounding.

L. Appendix. (As before ~~or None~~)

re of Present Survey: (Afloat and in dry dock)

Docking:- Wear and tear repairs.

Recommendation:

SUBMITTED record of DS 5,61 be assigned.

DS 5,61

~~DELETE FROM S.R.L.~~
~~Drydocking (grounding).~~

~~IN S.R.L. APPENDIX.~~
Stem and stem plating etc. set in.
Keel plate No.2 and shell plate
A.2 (p.s.a) indented.

~~ENGINEER SURVEYORS TO NOTE.~~



© 2021

Lloyd's Register
Foundation

012273-012278-0091

Handwritten notes: 5030, 13/6/61