

4.

Port of New York, N. Y.

June 18, 19 47

## REPORT ON MASTS, SPARS, AND RIGGING.

Sirs:

Having, in accordance with your instructions, examined  
Masts, Spars, and Rigging, and Iron Work of same, of the

SEDAN Register of U.S.A. #82245 At Todds Hoboken, N. J.

ve to report that I found

temast and fore topmast stays missing.

rt and Starboard fore topmast back stays bad; Recommend to be renewed.

commend that all goosnecks and pins be lifted from sockets for inspection;

turnbuckles be opened and freed; All rigging be wire brushed and coated.

Fee \$20.00

to the Surveyors,

Lloyd's Register of Shipping,

*Charles Tomrop*

X-12-42 Printed in U.S.A.



© 2021

Lloyd's Register  
Foundation

012346-012357-0243