

S.S. "GRAVENSCHON" ex "SEDAN"

New York Rpt. No. 47899


The Surveyors' reports on the electric propulsion equipment and the electric power and lighting installation have been examined in conjunction with the plans forwarded, and the propelling machinery and electrical installation, as reported and shown on the plans, is considered such as could be accepted for classification.

It is concluded, but should be confirmed by the Surveyors, that the varnished cambric insulated propulsion alternator and motor cables have a sheath of re-inforced rubber in addition to the bronze tape reported as the rubber sheath is required by both A.I.E.E. Standards and by the regulations of the American Bureau of Shipping.

Geo.

27.11.47.

Geo.



© 2021

Lloyd's Register
Foundation

012346-012357-0250