

Ship's name

"APEXITY"

Port

Gls.

No94158

GB

Class is subject to indented sheerstrake plates Nos. 1 & 2 from
forward with structure in way (p.s.) being examined and dealt
with as necessary by the Special Survey. Last survey date 6.12.62

S.R.L. Appendix (~~XXXXXXXXXX~~ none)

Surveys due SPECIAL SURVEY (C) due 10,61. Postponement until 10,62
approved 13.9.61. G.E. held Gls.8,61.

Nature of present survey (afloat and in drydock)

Docking: Special Survey: Damage repairs (various causes) and to
the deferred items as above:

Equipment - renewal and verification of 60 fms. of chain cable.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

NONE.

SS proposed to be completed by

~~XXXXXXXXXXXX~~

NOTED.

'DS 12,62' 'SS 12,62'
Without special conditions.

DS 12,62

SS 12,62 Without.

SPK
4/1/63

CERTIFICATE WRITTEN



© 2021
C&S Records Dept.
to note.

Lloyd's Register
Foundation