

24 OCT 1957

Received from Chief Ship Surveyor.....

SHIP'S NAME "MEIJI MARU"

REPORT Kob. No. 4975

Standing Conditions of Class: Subject to No.1 keel plate and bottom plates A.1 & 2 (p & s) in way of sternframe (locally doubled) being specially examined and dealt with as necessary next drydocking.

Assessment of Certificate (~~As before~~ or None)

Days due: SPECIAL SURVEY (A) due 9,57 - commenced Kob. 8,56 and subsequently advanced.

Where of Present Survey: (Afloat and in dry dock)

Completion of Special Survey: ~~XXXXXXXXXXXXXXXXXXXX~~

Special Features:

Interim Certificate in order (Yes ~~No~~ None)

Defects Outstanding: (If any for S.S.)

NONE.

~~to be completed by~~

Recommendation:

SUBMITTED record of 'DS 8,57' and NOTATION of 'SS Kob. 8,57' be assigned as recommended, subject as above.

C.S.S. Records Dept. 
to note.


DS 8,57
SS Kob. 8,57 Subject

IN L.O.E.
(Main structure partly of P.403 Steel).

IT IS FURTHER SUBMITTED the Surveyors be requested to forward copies of arrangement of repairing (fracture) in cargo tanks and reinforcement in way of A.P.tank as these do not appear to have been received.

See letter 10/2/58 ✓ 2910



© 2021  16/10/57
Lloyd's Register Foundation
012377-012385-0344