

# Lloyd's Register of Shipping

UNITED WITH THE BRITISH CORPORATION REGISTER



Port NEW YORK

May 9, 1957

UC-751

## This is to Certify that

E. G. DONALD and E. S. WITOWSKI

the undersigned Surveyors to this Society did at the request of

J. S. Coffin Company, attend at their works in Englewood, N.J., on the 18th March, 1957 and subsequently, for the purpose of examining and witnessing tests on One (1) Steam Turbine Centrifugal Feed Pump, Serial No. 5281 CG stated to be to the order of Heisi Kaiun and intended for installation in S/T "HEI TAI MARU".

J. S. Coffin Company Reference No. 30908.

The castings were made and tested in accordance with the requirements of this Society and the materials and workmanship of the completed unit are good.

Hydrostatic tests on the steam chest, turbine and pump casings were witnessed by the undersigned, and these were found sound and tight.

On completion of assembly, the unit was operated, in the presence of the undersigned, under varying conditions of load, the overspeed trip and back pressure relief valve tested with satisfactory results, and throughout the trials the unit was found to run free of mechanical troubles or vibration.

This unit is eligible, in my opinion, to be part of the machinery of a vessel classed, or contemplated class with this Society, subject to satisfactory installation and trials on board.

For purposes of identification, the unit has been stamped as follows:

LOYD'S NYK NO. 5114  
MARCH 26, 1957  
B. S. W.

E. G. Donald & E. S. Witowski  
Surveyors to Lloyd's Register of  
Shipping.

This Certificate is issued upon the terms of the Rules and Regulations of the Society which provides that—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed it is to be understood that neither the Society nor any Member or any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors or in any entry in the Register Book or other publication of the Society or for an error or omission in default of negligence of any of its Committees or any Member thereof, or the Surveyors or other Officers or Agents of the Society."

(Ref ID) 5M-45



Lloyd's Register  
Foundation  
012377-012385-0349