

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen, London

Telephone: ROYal 3551 (6 Lines)

23rd April, 1954.

sn(S)
AC

Dear Sirs,

Motorship "DAVANGER"
Messrs. Lithgows Ltd., Yard No.1079

With reference to your Certificates Nos. C.3167 and 8 respecting the 250 B.H.P. auxiliary engines fitted on board the above vessel, I would remind you that it is necessary to report on a form 4c all auxiliary engines which are required by the Rules to have torsional vibration characteristics investigated, and shall be glad if you will be guided accordingly in all future cases.

Yours faithfully,

pro Clerk to the
Classification Committee

The Surveyors,
MANCHESTER.



© 2021

Lloyd's Register
Foundation

012446-012459-0184