

Enclosure

23rd September, 1958.

Dear Sir,

Classn (3)

Djawatan Pelajaran Vessels

JW/53

I duly received your cablegram of the 20th August and letter of the 5th instant, from which it is noted it has been decided to withdraw the above mentioned fleet from class with this Society.

These cases, as listed on the attached memorandum, have now received the consideration of the Committee, and instructions have been given for notations to be recorded in the Register Book indicating that the class of each ship has been withdrawn at the Owners' request.

In the case of the "BANGO", however, the ship's class was already qualified by the notation "Class suspended - surveys overdue 10,56" and in view of the fact that no arrangements have been made to carry out the overdue surveys, the Committee had no alternative but to expunge the class on account of non-compliance with the Society's Rules.

I shall be glad if you will inform the Owners accordingly.

If in future you are called in to survey any of these ships, there will be no objection to your holding an inspection as a part reclassification survey, but great care should be exercised in the preparation of any certificate, and if practicable, prior instruction should be obtained from this Office.

Yours faithfully,

T.J. McGinness Esq.,
DJAKARTA.

© 2021
Lloyd's Register
Foundation
Clerk to the
Classification Committee.

012460-012472-0243