

COPY.

Lloyd's Register of Shipping. ¹⁸ NOV 1948



Port AUCKLAND, N.Z.

30th. SEPTEMBER - 1948 .


-DONKEY- -PART-

This is to Certify that I have

Surveyed the Boiler and Machinery of the Twin Sc.M/S. "PUKEKO".
742.Tons Gross of NAPIER, N.Z. & No.31512. in the Society's Register
Book for :- ANNUAL BOILER SURVEY-DOCKING & REPAIRS :-Donkey Boiler
examined throughout; Safety Valves set to 150lb. working pressure.
Propellers, Outside Stern Bushes, Sea Connections and all Fastenings,
Steering Appliances (NEW)- 1947 - now examined,
and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have
Recommended that the record of classification be continued,
+ LMC- with a fresh Record of + LMC-CS.11,45. and DBS. 9-48.
9,48.
be made in the Register Book in the case of this vessel when
the survey has been completed.

Parts now examined: MAIN ENGINES:-Stard. Unit in detail throughout
with attachments; viz-Air Starting Compressor,
Pumps, Valves, Pipes, Fittings & Fastenings.
Port & Stard. Intermediate Shafts.
Valves, Cocks, Pipes & Strainers of the Pumping arrangements.
The Electrical Equipment in accordance with the Rules.
Fuel Storage & Daily Service Tanks with their Fittings & Connections.
Overhauling of the Engines tested under working conditions .

2.Pistons-(Spare ex.Ship). Intermediate Shaft Bearings remetalled.
Electric Hydraulic Steering Appliances No. 791. Hyland as per Rules.
Certificates Sighted:


Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are
executed, it is to be understood that neither the Society nor any Member of any of its Committees is under
any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society
Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment,
negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of
the Society.