

Engine
Gross To
Less Crew
Less above
Engine
Tonnage

4m.5.16.

Received by Chief Ship Surveyor 17.6.16

Received from Chief Ship Surveyor

VESSEL'S NAME

Sheel Long Pinky

Rpt.

1st

No. 29372.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey

The Hull Surveyor should be requested
to state whether the bottom inside is cemented
as required by the Rules.

Dr. H. L. 17.6.16

17.6.16



© 2021

Lloyd's Register
Foundation

012514-012521-0221

BEAMS.