

Lloyd's Register of Shipping.

12 APR 1950

REPORT ON ANNUAL LOAD LINE SURVEY.

Name of Ship M.V. ESSO "SUWANEE" Official Number 168217 Port of Registry London
 Place of Survey Bowling Dates of Survey 21-3-50, 7-4-50 Date of last Load Line Survey 28-1-49

PARTICULARS OF SURVEY.

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
HATCHWAYS, INCLUDING SMALL HATCHWAYS.			
1. Exposed on freeboard deck.			
Coamings, their stays and stiffeners	Steel covers (Ringed) secured by toggles - Good.		
Beams			
Fore and afters			
*Covers			
*Tarpaulins (State number per hatchway)			
*Cleats and battens			
Lashings and their fittings			
Wedges (Is supply, including spares, adequate ?)			
2. Exposed on superstructure decks, including raised quarter decks.			
Coamings, their stays and stiffeners	/		
Beams			
Fore and afters			
*Covers			
*Tarpaulins (State number per hatchway)			
*Cleats and battens			
Lashings and their fittings			
Wedges (Is supply, including spares, adequate ?)			
3. Within superstructures not intact or not protected by Class I closing appliances.			
Coamings	/		
Beams			
Fore and afters			
Covers			
Tarpaulins (State number per hatchway)			
Cleats and Battens			
Wedges (Is supply, including spares, adequate ?)			
VENTILATORS IN EXPOSED POSITIONS.			
4. To spaces below freeboard deck.			
Coamings, their supports and deck connections	Good		
Closing arrangements	Good		
5. To spaces below decks of superstructure which are intact or closed by Class I appliances.			
Coamings, their supports and deck connections	Good		
Closing arrangements	Good		
AIR PIPES.			
6. Exposed on freeboard and superstructure decks.			
Closing arrangements	Good except	2 wood plugs supplied.	7-4-50.
7. Within partially enclosed superstructures.			
Closing arrangements	✓		
MACHINERY CASINGS.			
8. Casing Top.			
Fiddle openings, their covers and fastenings	✓		
Skylights, their fastenings, covers and lashings	Good		
9. Exposed on freeboard and raised quarter decks.			
Doors and fastenings	✓		
10. Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings	Good		
11. Within partially enclosed superstructures.			
Doors and fastenings	✓		
12. FLUSH BUNKER SCUTTLES and chain attachments			
	Good except	Chain attachment repaired.	7-4-50.
13. COMPANIONWAYS, including deckhouses enclosing ladderways.			
Doors, fastenings, covers	Good except	Toggles released.	7-4-50.

* Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Board of Trade Circular 1687, paragraph 117 (i)).

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
14. CLOSING APPLIANCES FOR OPENINGS IN SUPER-STRUCTURE BULKHEADS.			
Forecastle ...	Good ✓		
Bridge, fore end ...	✓		
Bridge, after end ...	Good ✓		
Poop ...			
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures ...	✓		
16. SCUPPERS AND SANITARY DISCHARGE PIPES.			
Valves ...	Good. ✓		
17. SIDE SCUTTLES AND DEADLIGHTS ...	Good except ✓	Glass renewed. ✓	7-4-50
18. GUARD RAILS ...	Good ✓		
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways ...	✓		
20. LIFELINES (fittings and material) ...	Good ✓		
21. FREEING PORTS.			
Shutters ...	✓		
Protection bars ...	✓		
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances ...	✓		
23. ITEMS NOT INCLUDED IN THE FOREGOING.			
24. LOAD LINE MARKS ...	Good except ✓	Letters out in, marks repainted ✓	7-4-50

Certificate A. To be signed by Surveyor in respect of a partial or complete survey.

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Board of Trade Circular 1687, and the requisite details of the survey have been entered herein.

Index Nos. of items examined. <small>(† Insert "all" in case of a complete survey.)</small>	Signature of Surveyor.	Place.	Date.
all	J. A. Tait.	Bowling.	7-4-50.

Certificate B. To be signed by Surveyor completing the survey.

I am satisfied

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have been maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor J. A. Tait. Place Bowling Date 7th April, 1950.

Signature J. A. Tait.


Date 11th April, 1950.

Fee 2

Number of Visits 2

Particulars of any change from the conditions given on the Load Line Certificate or on Form C 11 should be reported on Form C 11 (contd.) and attached to the Form C 11 on the Ship, a copy being forwarded to the Freeboard Department.

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a certified copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.



© 2021

Lloyd's Register
Foundation