

RAMS: „LLOYDREG“, ROTTERDAM

TELEPHONE No. 135355 (5 lines)

RECEIVED

5 - FEB 1963

Ans'd.....



Lloyd's Register of Shipping

ROTTERDAM, 4th February, 1963
Westblaak 32, P.O. Box 701

communications to be addressed to
THE SURVEYORS

reference:

Classing

reference:

RvA

Dear Sir,

" SOUTHERN CLIPPER " now " BITTERFELD "

The above ship changed Ownership in this Port on
the 30th January, 1963.

The new Owner's representatives have requested the
Lloyd's Register Class to be withdrawn as from now.

It has been stated that the ship will be classed with
the Deutsche Schiffs- Revision und Klassifikation (DSRK).

New particulars are:

Name: " BITTERFELD "

Owners: Deutsche Seereederei, Rostock.

Managers: Deutsche Schiffsmaklerei

Port of Registry: Rostock, German Democratic Republic.

Signal letters: D C Z S.

Yours faithfully,

The Secretary,
LONDON



© 2021

Lloyd's Register
Foundation

012585 - 012590 - 0030

REPORTS

PUBLICATIONS

USA
Rot 18-1 DAM

Rules Noted 6.2.

ALPHABETICALLY

Official correspondence should be addressed to the Director, Lloyd's Register, 15, Abchurch Lane, London, E.C. 4.

For information, please refer to the "Lloyd's Register" Handbook, which is available on request.

For further details, please contact the Registrar, Lloyd's Register, 15, Abchurch Lane, London, E.C. 4.

The Registrar, Lloyd's Register, 15, Abchurch Lane, London, E.C. 4, is responsible for the registration of companies and the issue of certificates of incorporation.

For information, please refer to the "Lloyd's Register" Handbook, which is available on request.

For further details, please contact the Registrar, Lloyd's Register, 15, Abchurch Lane, London, E.C. 4.

The Registrar, Lloyd's Register, 15, Abchurch Lane, London, E.C. 4, is responsible for the registration of companies and the issue of certificates of incorporation.



© 2021

Lloyd's Register
Foundation

MADE IN THE U.S.A.
REGISTERED IN THE U.S.A.

Lloyd's Register of Shipping