

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

FOUNDED 1780

RE-CONSTITUTED 1834

## Certificate of Class

Motorship "MILIANA"  
Official Number - Port of Registry Marseilles  
Owners Cie. Nouvelle de Navigation Busck S.A.  
Builders, and where and when built Rolandwerft G.m.b.H., Bremen, April, 1956

### REGISTERED TONNAGES

Gross 1133.07  
Net 439.30

### MOULDED DIMENSIONS

Length 257' 7"  
Breadth 38' 0 $\frac{1}{2}$ "  
Depth 23' 5"

This is to Certify that this Ship has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the 10th April, 1956. in a fit and efficient condition as is prescribed by the Society's Rules for the safe carriage of dry and perishable or other approved Cargoes, and has been **CLASSED** and entered in the REGISTER BOOK of this Society, with the Character **✠100A1**

subject to Periodical Surveys as required by the Rules.

The approved minimum freeboards from the deck line are as follows:—

Tropical	<u>114</u> feet <u>mm.</u> inches (T).	Winter	<u>260</u> feet <u>mm.</u> inches (WNA).
Summer	<u>114</u> feet <u>mm.</u> inches (S).	North Atlantic	
Winter	<u>210</u> feet <u>mm.</u> inches (W).	Allowance for fresh water for all freeboards	<u>96</u> mm. inches

Witness my hand,

W. J. Ferguson  
Secretary,

for Chairman.

71, Fenchurch Street, London, E.C.3. 10th July, 1956.

N.B.—If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—


"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2021

Lloyd's Register  
Foundation





© 2021  
012891-012897-0237

Lloyd's Register  
Foundation