

10 MAR 1966

SHIP'S NAME

"SILVER BAY"

PORT

SNG

No.

18878

APPDX.....(M)

LAST SURVEY DATE

1.2.66.

CLASS IS SUBJECT TO

1. Water box of auxiliary condenser be renewed by 3.66.
2. Ballast pump water end valve chest be renewed by 3.66.

Propeller examined afloat - due to damage stated
caused by striking unknown object, and
found one blade end missing. Opposite
blade trimmed to suit balance and it is
recommended propeller being repaired/renewed
at next D.D.

It is submitted that this
vessel is eligible to remain
as CLASSED. Subject as recommended, and as
above

A 8/3/66.



© 2021

Lloyd's Register
Foundation