

16th December, 1960.

two.

KOBE

8370, 75, 77, 92, 414 - As recommended.

RMC 8251, 96, 365 - As recommended.

"KIRISHIMA MARU" 8352 - As recommended, except that the notation SS 10.60 has been assigned at this time.

8410 "NISSHUN MARU" - As recommended, except that as the exhaust gas heated economiser safety valves still require to be adjusted the notation ABS 11.60 has not been assigned at this time, you should, therefore, issue an amended Interim Certificate stating the item remaining to complete the survey and forward a copy to this Office.

It is concluded that both auxiliary boilers were examined and their safety valves adjusted, but your confirmation is desired.

8347 "SUVA BREEZE" - As recommended, postponement of the Special Survey until January, 1961 having been approved.



© 2021

Lloyd's Register  
Foundation

012610-012612-0088