


COPY

## LLOYD'S REGISTER OF SHIPPING

Port Adelaide, Sth. Aust.24th March, 1965.

**This is to Certify** *that I have surveyed part of the machinery*

of the S.S. "INCHCASTLE", 5622 *Gross tons* of Hong Kong

*for* Advancement of Main Boiler Survey and B.W. repairs to the Starboard Boiler front end plate on account of grooving, whilst lying afloat at this port on the 18th March, 1965 and subsequently

*and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following*

*survey records assigned* MBS 11,64 as previously recommended when the survey has been completed subject to the Centre Boiler not being used until repaired and surveyed as previously recorded.

Parts now examined:— FOR MBS

Starboard Boiler surveyed throughout.

TO COMPLETE THE MBS: The Starboard Boiler to be examined under steam and its safety valves adjusted, also, the oil burning system and remote controls to be examined working.

*S.R. Thomas*  
(Sgn.) S. R. THOMAS.  
Surveyor to Lloyd's Register of Shipping

## KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey	MBS Main Boiler Survey	TS Tallshaft Survey
CSM Continuous Survey of Machinery	FP Fitted for oil fuel (date) FP above 150° F.	TS(CL) Tallshaft Survey—Continuous Liner
DBS Donkey Boiler Survey	SGS Steam Generator Survey	TSN Tallshaft renewed
ES Engine Special Survey	SPS Steampipe Survey	TS(OG) Tallshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."