


COPY

June Apt. 8

No.

10551

LLOYD'S REGISTER OF SHIPPING



B-79811

Port KOBEDate 7th June, 1962.

This is to Certify that I have
Surveyed the s.s. "INCHCASTLE" 5622 tons gross of Hong Kong on the 25th
May, 1962 and subsequent dates whilst afloat at Kobe on account of Damage
stated to have been sustained by encountering heavy weather on the 3rd
March, 1962 whilst on a voyage from Tahsis, B.C. to Tokyo in loaded
condition

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report, stating that all repairs recommended by
me have been completed to my satisfaction, also that I will
Recommend that she ~~be~~ remain as present classed in the Register
Book without fresh record of Docking subject to Shell Plate 4th below
sheer in way of No. 4 hold starboard side forward temporarily repaired
by welded doubling being examined and dealt with as found necessary
next dry-docking.

Arthur McLean
H. McLean.

Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

AS Annual Survey
BiS Biennial Survey
DS Docking Survey
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
SS(Dr) Hull Special Survey (Drilling)
SS(M) Hull Special Survey (Modified)
SS(P) Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."