

26 JUN 1944

fld. 2151.

Index No.

35487

## Lloyd's Register of Shipping.

Ship's Name ~~WINGLO-INDIAN~~ LUCKY

Official No. 166338

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines  
in

The following alterations have now been carried out and found satisfactory:-

In way of additional accommodation for gunners in starboard after tween decks

6 sidelights fitted, each 10" diameter, with hinged C.I. deadlights.

2 - 9" diameter ventilators fitted on upper deck, leading to new accommodation  
in tween decks, coamings 2'6" high 5/16" thick, with wood plugs & canvas covers.

1 - 24" diameter escape hatch from tween deck fitted on upper deck, with hinged  
bolted lid operated from both sides (Admiralty pattern).

1 - W.C. discharge and 1 washplace discharge fitted in tween decks, fitted  
with storm valve and non-return valve.

A steel companionway of substantial construction, fitted on starboard side of  
upper deck, against existing sidehouse, and leading to new accommodation in  
tween decks. Door coaming 18" high, hinged wooden door & spring lock.

*A. W. B. Edwards*

Surveyor to

Lloyds Register of Shipping

Hull. 17/6/44

*Noted*  
*20 JUN 1944*  
*J.P.S.*

© 2021

Lloyd's Register  
Foundation

012663-012668-0132.1