

1,500,10,59 Blk.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

GB

SHIP'S NAME m.s. "SOLVANTI"

REPORT Gro. No. 2025a

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

L. 180'-5"

B. 30'-0"

D. 11'-11½"

This ship is reported to have been built under Special Survey in conformity with or by standards equivalent to the Society's Rules and Regulations and the Secretary's letters.

IT IS THEREFORE SUBMITTED the ship is eligible to be classed:-

*100A1

OSD; 1 dk & pt S.dk; LF at btm; pt EW.

Mchy Aft

O.L. 195'-10"

E.B. 30'-5"

ESD; DF.

DBf pt W.B. 197t pt O.F; FPTs 86t; APTs pt W.B. 23t.pt O.F. pt F.W.

3BH; LACP.

P 52' F 29'

R.O.F: Nil

"k"

IT IS FURTHER SUBMITTED the Surveyors be advised it is concluded towline and mooring ropes have been supplied in accordance with Rule requirements as this is not stated in their report.

See letter
dated 26/2/60

1.2.60.

R.S.



© 2021

Lloyd's Register
Foundation

012678-012685-0231