

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

8th December, 1964.

C.
DHGK/BN

Dear Sirs,

M.S. "INDIAN REEFER"

With reference to your letter of the 27th November you may inform the Owners that the Committee have now deleted the condition of class relating to the Metalock repairs to the port forward outboard auxiliary engine entablature.

Yours faithfully,

Deputy Clerk to the
Classification Committee.

The Surveyors,
ODENSE



© 2021

Lloyd's Register
Foundation

012705-012710-0227