

22 JUL 1964

Ship's name

^{W/V.} INDIAN REEFER -

Port

Antes

No. 1043.

Class is subject to Port. for'd. outboard aux. engine Last survey date 12/6/64
entire hull (multilock 10/62 & 4/63) bin examined by ~~11/4/65~~ 12/6/65. (12 hrs.)

Repair.

To P.Y.S. M.E. L.P. fuel pump & governor drive shafts
bearing brackets.

C.S. Advanced.

It is submitted that this
vessel is eligible to remain
as CLASSED, subject to exam.

^{100%}
22/7/64



© 2021

Lloyd's Register
Foundation