

Ship's name *Central 60*

Port *B.A.S*

11 0 JUN 1965
No. *37743*

App Note as under
Class is subject to ① Found and scavenge blower rotor being

dealt with as necessary by 5.65

② M/E N° 5 cylinder cover being specially examined
by 5.65 (6 months)

③ M/E N° 5 turbo supercharger rotor shaft & aft bearing
being specially examined & dealt with as found
necessary on vessels arrival at B.A at end of present voyage.

ABS due 2.65, remain 2.64 not advanced

Subject ① above continues efficient & its submitted
limit be extended to 7.65 pending delivery of ship spare
unit after reconditioning

Subject ② specially examined & remains efficient Subject to
delete & note in Appendix

Subject ③ now dealt with by fitting ships reconditioned
spare unit - Subject to delete.

It is submitted that this
vessel is eligible to remain
as **CLASSED**. Subject as ① above only now amended.

G
10/6/65.

To complete ABS:- EG boiler SV to be adjusted

Appendix Note :- M/E N° 5 cyl cover (EW 11.64)