

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 { Overseas: Committee London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

21st May, 1965.

C.
MWK/DET

Dear Sirs,

M.S. "CUTRAL CO"

Following a survey carried out at Galveston on the 1st April, it was recommended that main engine No.5 turbo supercharger rotor shaft and after bearing be specially examined and dealt with as found necessary on the ship's arrival at Buenos Aires at the end of the present voyage.

In the circumstances, I shall be glad to learn whether this matter has yet received attention.

Yours faithfully,

Assistant Clerk to the
Classification Committee

The Surveyors,
BUENOS AIRES.



© 2021

Lloyd's Register
Foundation

012711-012715-0191